Attachment C

| | Summary of Distribution Circuit Field Inspection by ICC Staff | | | | | | |
|-------|---|--|------------|--|--|--|--|
| Utili | ity: | IP | Date: | 5/21/02 | | | |
| Circ | uit: | Belleville 163 (Belleville & rural Freeburg) | Inspector: | J. D. Spencer, J. L. Prange, & Bev Hall (IP) | | | |

Gen. Notes: Tree trimming looked very good on this circuit, with many opportunities for problems and few tree clearance problems found. There are several lengthy inaccessible cross-country sections in this circuit, and some relatively small underground areas.

| Мар No. | Item Description | Photo(s) | Location |
|---------|---|----------|---|
| 7 of 36 | Blown lightning arrester cap | | 4th pole west of Old Freeburg Rd. (CH 4) along |
| 1 01 30 | | | Peabody Short Line RR |
| 11 | Woodpecker hole in pole | | Plum Hill Rd. at tap to Sta. 34785 |
| 11 | Woodpecker hole in pole | | First pole south of Sta. 17978 on Rentchler Rd. |
| 12 | 2 woodpecker holes in pole | | On Rentchler Rd. at first pole west of tap to Sta. |
| 13 | Broken ground wire | | 2nd pole west of Sta. 15106, west of Old Freeburg Rd. (in dead line section?) |
| 18 | Burned strands in 6A CWC primary (in primary phase conductor & neutral) | | 2 or 3 locations along Old Freeburg Rd. just south of Sugar Creek |
| 18 | No guy marker | | Old Freeburg Rd. & Schlueter Rd. |
| 18 | No guy marker | | Old Freeburg Rd. at tap to Sta. 14590 |
| 20 | Split pole top & woodpecker holes | | First pole north of tap to Sta. 14624 on White Oaks Club Rd. |
| 21 | Woodpecker holes in 2 poles | | At Sta. 22971 north of Jefferson Rd. (CH 20) and in 1st pole south of there |
| 23 | 5 woodpecker holes in pole | | 8th pole west of III. Rt. 15 in tap to Stas. 24876, 14615, 25072, & 25800 |
| 23 | 19 woodpecker holes in one pole | A23, A24 | 4th pole west of III. Rt. 15 in tap to Stas. 24876, 14615, 25072, & 25800 |
| 23 | Woodpecker holes in pole | | 2nd pole west of III. Rt. 15 in tap to Stas. 24876, 14615, 25072, & 25800 |
| 23 | Woodpecker holes in pole | | At Sta. 18811 in line west of III. Rt. 15 |
| 23 | Split pole top & several woodpecker holes | | 2nd pole west of Sta. 14620, east of III. Rt. 15 |
| 24 | Split pole top | | 3rd pole south of tap to Sta. 14627 on White Oaks Club Rd. |
| 24 | Split crossarm | | 4th pole south of tap to Sta. 14627 on White Oaks Club Rd. |

Attachment C

| Map No. | Item Description | Photo(s) | Location |
|---------|---|----------|--|
| 25 | Woodpecker holes in 3 poles | | Along Jefferson Rd. (CH 20)4th pole west of Reinneck Rd., 4th & 5th poles west of tap to Sta. 14639. |
| 28 | Shell rotted pole | | 3rd pole west of White Oaks Club Rd. in tap serving Stas. 25014 & 11189. |
| 28 | Split pole top | | 2nd pole west of White Oaks Club Rd. in tap serving Stas. 25014 & 11189. |
| 28 | Split crossarm | A22 | On White Oaks Club Rd. at 1st pole north of tap to Stas. 25014 & 11189. |
| 28 | Split crossarm | | On White Oaks Club Rd. at 2nd pole north of tap to Stas. 25014 & 11189. |
| 29 | Steel brace off of crossarm | | 2nd pole east of Sta. 14637 (near NE corner of map) |
| 32 | About 10 woodpecker holes in pole | A12 | On Jacks Run Rd. in 1st pole north of tap to Sta. 26452. |
| 32 | Split pole top & woodpecker hole in pole | A13 | At corner of Jacks Run Rd. & CH 65. |
| 32 | Woodpecker holes in pole | A15 | 1st pole north of corner of Jacks Run Rd. & CH 65. |
| 32 | Split pole top & woodpecker holes in pole | A14 | 2nd pole north of corner of Jacks Run Rd. & CH 65. |
| 32 | Split pole top & woodpecker hole in pole | A16 | 1st pole north of corner of Hertl School Rd. & CH 65. |
| 32 | Pole rotted at ground line, split & deteriorated crossarm, and neutral wood pin through arm | A17 | 1st pole south of corner of Jacks Run Rd. & Hertl School Rd. |
| 33 | Bad crossarm & floater (field-side phase) (Woodpeckers on pole at time of inspection) | A18-A21 | Jacks Run Rd. (CH 65) at 1st pole west of tap to Sta. 37145. |
| 33 | Broken ground wire | | Jacks Run Rd. (CH 65) at 1st pole west of Sta. |